Philips Triathlon Filter

Sleeve for dry vacuuming

FC6004

Protects the motor of your vacuum cleaner

Find matching products on the specifications tab

The inlet filter of your vacuum cleaner needs to be replaced periodically. Regular replacement guarantees an optimal suction power and protects the motor of your device against fine dust.

Ease of using Philips spare parts

- Renew your product with original Philips parts

PHILIPS

sense and simplicity

Filter
Sleeve for dry vacuuming

FC6004/01

Specifications

Replaceable part

- Fits product types: FC6841 - FC6845, FC6845, FC8334/01, FC8336/01, FC8338/01, FC8344/01, FC8344/02, FC8344/03, FC8347/01, FC8348/01, FC8380-8399, FC8400 - FC8439, HR6263 - HR6299, HR6400 - HR6800, HR6815 - HR6840, HR6838, HR8300 - HR8378, HR8500 - HR8599, HR8700 - HR8999, 8240XL, 8250XL, HQ8260, HQ8261, HQ8270, HQ8290, FC6841/01, FC6842/01, FC6843/01, FC6843/02, FC6843/03, FC6843/04, FC6844/01, FC6844/02, FC8380/01, FC8381/01, FC8381/02, FC8381/11, FC8382/01, FC8384/01, FC8386/01, FC8386/11, FC8388/02, FC8390/01, FC8390/02, FC8392/01, FC8394/01, FC8396/01, FC8396/02, FC8397/02, FC8398/02, FC8400/01, FC8402/01, FC8404/01, FC8406/01, FC8408/01, FC8408/02, FC8410/01, FC8412/01, FC8421/02, FC8422/01, FC8424/02, FC8425/02, FC8426/02, FC8426/03, FC8428/02, FC8429/02, FC8430/02, FC8432/01, FC8433/02, FC8433/03, FC8434/02, FC8436/02, FC8436/03, FC8437/02, FC8438/02, FC8439/02, FC8440/01, FC8442/01, FC8445/01, HR6283/05, HR6284/05, HR6460/01, HR6500/01, HR6500/89, HR6501/90, HR6518/93, HR6520/91, HR6540/89, HR6641/01, HR6642/01, HR6651/02, HR6651/03, HR6651/04, HR6655/01, HR6661/01, HR6661/02, HR6665/01, HR6675/01, HR6676/01, HR6700/89, HR6730/89, HR6760/89, HR6825/01, HR6834/01, HR6835/01, HR6835/02, HR6835/03, HR6835/04, HR6835/05, HR6836/01, HR6836/02, HR6836/03, HR6836/04, HR6839/01, HR6840/01, HR8310/01, HR8323/01, HR8330/01, HR8331/01, HR8345/01, HR8345/02, HR8346/02, HR8352/01, HR8352/02, HR8353/01, HR8354/01, HR8356/01, HR8356/02, HR8358/01, HR8358/02, HR8360/01, HR8360/02, HR8360/03, HR8361/01, HR8362/01, HR8364/02, HR8365/02, HR8368/01, HR8370/01, HR8372/02, HR8372/03, HR8372/04, HR8372/06, HR8374/02, HR8376/05, HR8376/07, HR8376/08, HR8378/07, HR8501/01, HR8502/01, HR8502/06, HR8503/01, HR8504/01, HR8505/01, HR8507/02, HR8507/09, HR8508/02, HR8508/16, HR8508/19, HR8514/01, HR8514/91, HR8525/02, HR8532/01, HR8532/02, HR8534/01, HR8536/01, HR8536/02, HR8536/05, HR8539/01, HR8539/02, HR8539/05, HR8542/01, HR8546/02, HR8556/01, HR8556/02, HR8564/01, HR8564/11, HR8564/91, HR8565/01, HR8565/02, HR8565/11, HR8565/12, HR8565/17, HR8566/01, HR8566/02, HR8566/05, HR8566/11, HR8566/12, HR8566/15, HR8566/19, HR8566/22, HR8567/01, HR8567/02, HR8567/04, HR8567/09, HR8567/11, HR8567/12, HR8568/01, HR8568/02, HR8568/04, HR8568/09, HR8568/11, HR8568/12, HR8568/18, HR8568/19, HR8568/25, HR8569/12, HR8569/17, HR8569/18, HR8570/12, HR8570/15, HR8570/38, HR8570/57, HR8571/15, HR8571/18, HR8572/11, HR8572/12, HR8572/18, HR8572/24, HR8572/28, HR8572/34, HR8573/12, HR8581/04, HR8581/10, HR8581/11, HR8582/14, HR8701/01, HR8704/02, HR8707/05, HR8731/01, HR8731/02, HR8731/05, HR8733/01, HR8733/05, HR8735/01, HR8735/02, HR8755/02, HR8755/04, HR8775/05, HR8825/02, HR8837/02, HR8847/01, HR8858/02, HR8880/01, HR8881/02, HR8882/02, HR8884/01, HR8891/06, HR8891/16, HR8891/17, HR8893/02, HR8893/06, HR8893/15, HR8895/17, HR8897/02, HR8897/03, HR8897/04, HR8897/06, HR8898/06, HR8899/01, HR8900/12, HR8900/14, HR8900/15, HR8900/17, HR8901/09, HR8903/02, HR8903/05, HR8903/09, HR8903/12, HR8903/15, HR8903/17, HR8907/02, HR8909/05, HR8910/09, HR8910/12, HR8910/15, HR8948/01, HR8948/09, HR8981/18, HR8982/15

Highlights

Easy replacement

From time to time your product needs a facelift, and with Philips consumer replacement parts to renew your product, it's never been so easy! All this with guaranteed Philips quality and 1:1 exchange.

Issue date 2013-01-10

Version: 4.0.1

© 2013 Koninklijke Philips Electronics N.V.
All Rights reserved.

Specifications are subject to change without notice. Trademarks are the property of Koninklijke Philips Electronics N.V. or their respective owners.

www.philips.com